



## Changsha Proxima Technology Co., Ltd.

Add.: Room 401-119, 4th Floor, Supporting Service Center, Building 1, Phase 2, Huanghua Comprehensive Bonded Zone A, Huanghua Town, Lingkong Block, Changsha Area, China (Hunan) Pilot Free Trade Zone

Email: info@dsfuelsystem.com      Tel: +86-13997800913

Contact: Lydia

### Catalog of Repair Kits for Bosch

Item	Repair Kits No.	Nozzle No.	Valve Kits No.	Injector No.
1	F 00R J0 3281	DLLA150P1622	F 00R J01 657	0 445 120 078
2	F 00R J0 3286	DLLA153P1721	F 00R J02 056	0 445 120 106
3	F 00R J0 3491	DLLA150P1781	F 00R J01 692	0 445 120 244
4	F 00R J0 3289	DLLA149P2166	F 00R J02 035	0 445 120 215
5	F 00R J0 3513	DLLA148P2222	F 00R J01 727	0 445 120 266
6	F 00R J0 3287	DLLA148P2221	F 00R J01 727	0 445 120 265
7	F 00R J0 3545	DLLA150P2386	F 00R J01 692	0 445 120 357
8	F 00R J0 3514	DLLA151P2240	F 00R J02 035	0 445 120 277
9	F 00R J0 3282	DLLA148P1688	F 00R J02 806	0 445 120 110
10	F 00R J0 3475	DLLA145P1655	F 00R J01 727	0 445 120 388
11	F 00R J0 3472	DLLA152P1690	F 00R J02 806	0 445 120 083
12	F 00R J0 3493	DLLA150P1826	F 00R J02 035	0 445 120 160
13	F 00R J0 3288	DLLA141P2146	F 00R J02 103	0 445 120 134
14	F 00R J0 3509	DLLA150P2197	F 00R J01 657	0 445 120 247/395
15	0 986 AD 3802	DLLA144P1565	F 00R J01 479	0 445 120 066
16	0 986 AD 3803	DLLA146P1581	F 00R J01 479	0 445 120 067
17	F 00R J0 3468	DSLA128P1510	F 00R J02 130	0 445 120 059
18		DSLA143P5501	F 00R J02 130	0 445 120 212
19	F 00R J0 3484	DSLA140P1723	F 00R J02 130	0 445 120 123
20	F 00R J0 3290	DLLA152P1768	F 00R J01 692	0 445 120 213/214
21	F 00R J0 3483	DLLA142P1709	F 00R J01 941	0 445 120 122
22	F 00R J0 3548	DLLA152P2344	F 00R J01 692	0 445 120 343
23	F 00R J0 3285	DLLA151P1656	F 00R J01 692	0 445 120 081
24	F 00R J0 3506	DLLA153P2189	F 00R J02 056	0 445 120232
25	F 00R J0 3546	DLLA145P2397	F 00R J02 103	0 445 120 361
26	F 00R J0 4262	DLLA147P2474	F 00R J01 727	0 445 120 391
27	F 00R J0 3507	DLLA150P2142	F 00R J02 472	0 445 120 242/383
28	F 00R J0 3509	DLLA150P2197	F 00R J01 657	0 445 120 395
29	F 00R J0 3475	DLLA145P1655	F 00R J01 727	0 445 120 086
30		DLLA146P1339	F 00R J02 466	0 445 120 218
31	F 00R J0 3506	DLLA153P2189	F 00R J02 056	0 445 120 309
32	F 00R J0 3549	DLLA149P2345	F 00R J01 692	0 445 120 344
33	F 00R J0 3283	DLLA152P1819	F 00R J01 692	0 445 120 224
34		DLLA135P1747	F 00R J02 266	0 445 120 126
35	F 00R J0 3482	DLLA144P1707	F 00R J01 941	0 445 120 121
36		DLLA118P2203	F 00R J01 941	0 445 120 236
37	F 00R J0 3486	DLLA143P1696	F 00R J01 727	0 445 120 127
38	F 00R J0 3515	DLLA142P2262	F 00R J02 472	0 445 120 289
39		DLLA149P2161	F 00R J02 506	0 445 120 199
40		DLLA145P1794	F 00R J01 819	0 445 120 157
41		DLLA143P2155	F 00R J01 714/2004	0 445 120 204/161
42	F 00R J0 3474	DLLA155P1052	F 00R J00 399	0 445 120 085
43	F 00R J0 3305	DLLA154P2406	F 00R J02 561	0 445 120 368
44	F 00R J0 4410	DLLA148P2516	F 00R J02 103	0 445 120 415
45		DLLA145P2533	F 00R J02 806	0 445 120 421
46	F 00R J0 3535	DLLA148P2369	F 00R J02 103	0 445 120 321
47		DLLA147P1814	F 00R J01 692	0 445 120 153
48	F 00R J0 3492	DLLA148P1815	F 00R J02 806	0 445 120 290
49		DLLA140P1790	F 00R J02 806	0 445 120 141
50		DLLA145P2168	F 00V C01 383	0 445 110 376
51	F 00R J0 3569	DLLA152P2422	F 00R J02 035	0 445 120 373
52		DLLA143P1696	F00RJ01727	0 445 120 389
53		DLLA149P2568	F00RJ01727	0 445 120 462
54		DLLA150P1666	F00RJ02806	0 445 110 293
55		DLLA148P1524	F00RJ01218	0 445 120 217

56		DLLA127P2402	F00RJ02472	0 445 120 367
57				2645A747
58				2645A749
59				3264700
60		DSLA143P970	F00RJ00339	0 445 120 007
61		DLLA146P1339	F00RJ01218	0 445 120 030
62		DLLA162P2160	F00VC01502 F00VC01517	0 445 110 647
63		DLLA145P2557	F00VC01353	0 445 110 808
64		DLLA156P2470	F00VC01367	0 445 110 677
65		DLLA135P1747	F00RJ02266	0 445 120 126
66		DSLA154P1320	F00VC01051	0 445 110 189
67		DLLA155P1493	F00VC01349	0 445 110 250
68		DLLA157P1424	F00RJ01428	0 445 120 048
69		DLLA150P1566	F00RJ01451	0 445 120 074
70		DLLA162P2266	F00VC01377	0 445 110 443
71		DLLA153P1609	F00VC01352	0 445 110 278
72		DLLA82P1773	F00VC01359	0 445 110 335
73		DLLA137P1648	F00RJ01819	0 445 120 092
74		DLLA155P1514	F00VC01349	0 445 110 249
75		DLLA134P2367	F00ZC01315	0 445 110 603
76		DLLA150P1734	F00VC01200	0 445 110 351
77		DLLA139P2229	F00VC01201	0 445 110 418
78		DLLA158P1385	F00RJ01159	0 445 120 027
79		DLLA148P1660	F00VC01202	0 445 110 419
80		DLLA147P1702	F00VC01359	0 445 110 445
81		DLLA154P1418	F00RJ01159	0 445 120 045