



## Changsha Proxima Technology Co., Ltd.

Add.: Room 401-119, 4th Floor, Supporting Service Center, Building 1, Phase 2, Huanghua Comprehensive Bonded Zone A, Huanghua Town, Lingkong Block, Changsha Area, China (Hunan)

Email: info@dsfuelsystem.com

Tel: +86-13997800913

Contact: Lydia

### Catalog of Repair Kits for Denso

Item	Valve Assembly No.	Applying Injectors
1	23670-0L050G 23670-0L050F	23670-0L020 23670-30370 23670-0L050 095000-829# 095000-8220 095000-856# 095000-592#
2	23670-30050G 23670-30050F	23670-30050 095000-5880 095000-5881 095000-5660
3	23670-30300G 23670-30300F	23670-30300 095000-7760 095000-7761 095000-7751 095000-7750 23670-39276
4	23670-30300G 23670-30300F	23670-0L010 23670-0L070 23670-30240 23670-09360 095000-874# 095000-593# 095000-738#
5	23670-0L090G 23670-0L090F	23670-0L090 294050-0521 23670-30400 295050-0460
6	095000-7781G 095000-7781F	095000-778X 23670-30280 23670-39185 23670-39215 23670-39315 23670-39310 23670-30140 23670-30220 23670-09070

7	23670-0L110G 23670-0L110F	23670-0L110 23670-30420 23670-09380 295050-054# 295050-074# 295050-081#
8	095000-5550G 095000-5550F	095000-5550 095000-8310
9	095000-5600G 095000-5600F	095000-5600 1465A041
10	095000-6366G 095000-6366F	095000-6363 095000-6364 095000-6366 (8-97609788-3) 095000-534x 8-97602485-6
11	095000-9560G 095000-9560F	095000-956x 1465A257 095000-749# 1465A297
12	095000-5760G 095000-5760F	095000-811# 095000-576# 1465A054 1465A307
13	095000-5471G 095000-5471F	095000-5471 095000-5470 095000-5473 095000-5474 095000-8900 095000-8901 095000-8902 095000-6373 095000-8903 095000-0660 (8-98284393-0)
14	095000-6353G 095000-6353F	095000-6353 095000-6350 095000-6352
15	095000-6593G 095000-6593F	095000-6593 095000-6591 095000-6592 095000-6594
16	095000-6480G 095000-6480F	095000-6480 095000-6481 095000-6482 RE529149 RE546776 RE528407
17	095000-6490G 095000-6490F	095000-6491 095000-6490 095000-6492 RE529118
18	095000-6310G 095000-6310F	095000-6310 095000-6311 RE530362
19	095000-1211G 095000-1211F	095000-1211 095000-1210
20	095000-6070G 095000-6070F	095000-6070
21	9709500-7510G 9709500-7510F	9709500-751x
22	095000-9690G 095000-9690F	095000-9690
23	095000-5800G 095000-5800F	095000-5800 095000-5801 095000-7060 6C1Q-9K546-BC
24	095000-8940G 095000-8940F	095000-8940 RE543266
25	095000-5007G 095000-5007F	095000-5007
26	23670-30310G 23670-30310F	23670-30310

27	23670-30080G 23670-30080F	23670-30080
28	23670-30290G 23670-30290F	23670-30290
29	295050-0100G 295050-0100F	23670-30190 23670-30196 295050-0100
30	23670-51040G 23670-51040F	095000-8060 095000-9770 23670-51040
31	23670-51030G 23670-51030F	095000-7711 095000-9780 23670-51030
32	095000-5650G 095000-5650F	095000-5650
33	095000-6252G 095000-6252F	095000-625X 16600-EB70D
35	095000-8370G 095000-8370F	095000-8370
36	095000-6244G 095000-6244F	095000-6244
37	295050-1060G 295050-1060F	295050-1060
38	23670-30410G 23670-30410F	23670-0L100 295050-0190 295050-0530 23670-30410 295050-0470
39	23670-5511G 23670-5511F	095000-5511 8-97603415-8 095000-5512 095000-5517 8-97603415-8 095000-5513

40	095000-6520G 095000-6520F	095000-6520
41	095000-6252G 095000-6252F	095000-625X 16600-EB70D
42	095000-5226G 095000-5226F	095000-5226 23670-E0341
43	23670-30410G 23670-30410F	23670-30410 295050-0470
44	295050-0896G 295050-0896F	095000-0896 1465A367
45	095000-6320G 095000-6320F	RE530361 095000-632#
46	095000-6980G 095000-6980F	095000-698#
47	095000-8340G 095000-8340F	095000-8340 8-97435030-0 8-98106693-1
48	23670-0E010F	3670-0E010 295700-0550
49	23670-0E020F	23670-0E020 295040-9440 295700-0560
50	095000-5050G 095000-5050F	095000-5050
51	095000-6640G 095000-6640F	095000-6640 6251-11-3200
52	095000-6470G 095000-6470F	095000-647# RE529151

Note: "G" is with stem electric repair kit; "F" is without stem electric repair kit.